


🚺 Ēxist. Elevations WEST



Elementary School T.O. Conc.

SCALE: 1/16" = 1'-0"

ASSESSMENT & FINDINGS

ELEMENTARY SCHOOL

STRUCTURE

- ROOF FRAMING: PLATE CONNECTED WOOD TRUSSES AT 24" O.C. ORIGINAL DRAWINGS SHOW TRUSSES DESIGNED TO SUPPORT OWN DEAD LOAD, AS WELL AS 50 PSF SNOW LOAD
- 1ST FLOOR: CONCRETE SLAB ON GRADE WITH EDGE INSULATION (PER ORIGINAL DWGS)
- FOUNDATION: CAST-IN-PLACE CONCRETE, NO EVIDENCE OF FROST HEAVING OR SETTLEMENT

ENVELOPE

- METAL ROOFING
- VINYL SIDING AND METAL TRIM STARTING TO DEGRADE DUE TO AGE AND SUN EXPOSURE, THOUGH NO SIGNIFICANT AREAS OF DAMAGE, ROT OR SIGNS OF WATER INTRUSION WERE FOUND.
- SOME MOLD ON NORTH ELEVATION SIDING AND TRIM
- TOPOGRAPHY OF SITE DOES NOT PROVIDE FOR THE POTENTIAL TO ADD A FOOTING DRAIN, THEREFORE WATER TABLE/MOISTURE CANNOT BE ELIMINATED
- WINDOWS, DOORS APPEAR IN SERVICEABLE CONDITION

STRUCTURAL RECOMMENDATIONS:

- OVERALL, THE BUILDING APPEARS IN VERY GOOD CONDITION AND SUITABLE FOR USE AS A PUBLIC BUILDING
- RE-GRADE ANY AREAS OF NEGATIVE DRAINAGE AROUND THE BUILDING
- PROVIDE AN ATTIC ACCESS HATCH FOR ON-GOING OBSERVATION AND MAINTENANCE.

USE AND OCCUPANCY:


- 8008 SF 1ST FLOOR < CODE MAX AREA FOR ASSEMBLY (A-1) OCCUAPANCY FOR SPRINKLERED, 1 STORY BUILDING THEREFORE, NON-SEPARATED USES (NO REQUIRED FIRE RATINGS) REQUIRED BETWEEN OTHER LOWER HAZARD OCCUPANCIES.

ACCESSIBILITY:

- PRELIMINARY REVIEW SHOWS COMPLIANT ACCESSIBLE ROUTE TO ACCESS AND CIRCULATE THROUGH THE BUILDING
- RESTROOMS: ASPECTS ARE NON-COMPLIANT, NAMELY MANEUVERING CLEARANCES AT WCs.

ENERGY CODE:

- ASSEMBLIES ARE CLOSE TO COMPLIANCE WITH CURRENT REQUIREMENTS.
- CHANGE OF USE/OCCUPANCY MAY TRIGGER FULL COMPLIANCE WITH WHICH COULD RESULT IN ADDITION OF INSULATION TO ROOF AND WALL ASSEMBLIES.



ASSESSMENT & FINDINGS

TOWN HALL

STRUCTURE

- ROOF FRAMING: 2x6 TRUSSES (1x4, 1x8 WEB)
- 2ND FLOOR FRAMING: 2x10 JOISTS AT 24" O.C.,
 - SUPPORTED BY SINGLE 5 1/2"W x 8" CENTER BEAM ON 16' O.C. COLS
- 1ST FLOOR: CONCRETE SLAB ON GRADE WITH POSSIBLE WOOD FRAMING BURIED IN THE SLAB
- FOUNDATION: DRY-LAID FIELD STONE REACHING APPROX. 22" BELOW GRADE. USDA SOIL MAPS SHOW SILTY SOILS WITH WATER TABLE 18"-36" BELOW GRADE

ENVELOPE

- METAL ROOFING
- WOOD TRIM AND CLAPBOARDS ARE IN POOR CONDITION, REQUIRING AT A MIN DEEP PREP AND RE-PAINTING, SOME REPLACEMENT
- SOME AREAS OF SIDING NEAR GRADE SHOW MOLD AND ROT
- WOOD FRAMING IS CLOSE TO GRADE. SPLASH BACK FROM ROOF RUNOFF AND MOISTURE FROM CAPILLARY ACTION HAVE CREATED CONDITIONS SUSCEPTIBLE TO ROT.
- TOPOGRAPHY OF SITE DOES NOT PROVIDE FOR THE POTENTIAL TO ADD A FOOTING DRAIN, THEREFORE WATER TABLE/MOISTURE CANNOT BE ELIMINATED

STRUCTURAL RECOMMENDATIONS:

- FOUNDATION: IN ORDER TO PROVIDE MOISTURE AND THERMAL ENVELOPE SUITABLE FOR LONG-TERM USE OF THE BUILDING, A NEW FOUNDATION SHOULD BE CONSIDERED FOUNDATION REPLACEMENT OPTION:
 - JACK BUILDING AND LIFT TO ALLOW ACCESS
 - REMOVE AND REPLACE EXISTING FOUNDATION
 - REMOVE AND REPLACE (OR BUILD OVER) THE EXISTING FLOOR SLAB
 - REPLACE/REPAIR SILLS
 - REGRADE AROUND THE BUILDING TO PROVIDE POSITIVE DRAINAGAE AWAY
 - PLACE BUILDING BACK ON NEW FOUNDATION IDEALLY SLIGHTLY ELEVATED
- 2ND FLOOR FRAMING:
 - EXISTING JOISTS ARE SUITABLE FOR ASSEMBLY, OFFICE OCCUPANCIES
 - REINFORCE OR REDUCE SPAN OF MID-SPAN BEAM
- ROOF FRAMING:
 - EXISTING CAN BE LEFT AS-IS IN SHORT TERM. IF INSULATION ADDED TO ATTIC OR IF ROOFING IS TO CHANGE, RAFTERS SHOULD BE REINFORCED.


USE AND OCCUPANCY:

- BUILDING AREA < CODE MAX AREA FOR ASSEMBLY (A-1) OCCUAPANCY FOR UNSPRINKLERED, 2-STORY BUILDING, THEREFORE, NON-SEPARATED USES


ACCESSIBILITY:

- NON-COMPLIANT ACCESSIBLE ROUTE AND RESTROOM FACILITIES ENERGY CODE:
 - CHANGE OF USE/OCCUPANCY MAY TRIGGER FULL COMPLIANCE

ISLE LA MOTTE









SCHEME 01

ELEMENTARY SCHOOL

PROS

- THE SPACE IS LARGELY BEING USED IN A SIMILAR FUNCTION AS IT WAS ORIGINALLY INTENDED
- REQUIRES MINIMAL STRUCTURAL UPDATES
- THE EXISTING ENTRIES AND EXITS SUPPORT THE NEW PROGRAM

CONS

- LIGHTING IN THE CENTRAL AREA WILL REMAIN AN ISSUE WITHOUT ADJUSTING THE EXISTING ROOF.
- THERE MAY BE NOISE ISSUES HAVING CHILDCARE LOCATED SO CLOSELY TO MUNICIPAL OFFICES.

TOWN HALL

PROS

- CONVERTING TO RESIDENTIAL IS APPROPRIATE FOR THE SCALE OF THE BUILDING.
- COULD CREATE AN ADDITIONAL SOURCE OF REVENUE FOR THE TOWN.

CONS

- THERE ARE A LOT OF STRUCTURAL UPDATES THAT WOULD BE REQUIRED BEFORE BEGINNING THE RENOVATION
- THE TOWN WOULD LARGELY LOSE ACCESS TO A HISTORICALLY COMMUNITY SPACE

SCHEME 02

ELEMENTARY SCHOOL

PROS

- CREATING A REVENUE SOURCE FOR THE TOWN
- CREATES WELCOMING GREEN SPACES

CONS

- THIS WOULD REQUIRE A LARGE STRUCTURAL EFFORT.
- WOULD BE LOSING A PORTION OF THE EXISTING SQUARE FOOTAGE OF CONDITIONED SPACE

TOWN HALL **PROS**

- - THE BUILDING WOULD LARGELY BE SERVING IT'S ORGINAL PURPOSE
 - CELEBRATING A "HISTORIC" PART OF THE COMMUNITY

CONS

- LIMITED PARKING
- THE COST TO INSTALL A LIFT TO BRING UP TO ACCESSIBLITY CODE

SCHEME 03

ELEMENTARY SCHOOL

PROS

- CREATES A CENTRAL HUB FOR THE TOWNS OPERATIONS
- UTILIZES THE EXISTING BEARING WALLS AND MAY LEAD TO MODEST STRUCTURAL COSTS

CONS

- ADDED EXPENSE OF ADDITIONAL PAVING FOR GARAGE BAY ENTRIES
- SEPARATING THE COMMUNITY SPACE AND THE TOWN GARAGE COULD BE TRICKY.

NEXT STEPS

1. 12/18 NOTES:

SHKS TO ISSUE CLEAN SET OF MEETING SLIDES WITH LIVE MEETING NOTES/MARKUPS. ALSO SEND STRUCTURAL ASSESSMENT

2. PUBLIC MEETING

TARGETING END OF MARCH (POST-ELECTIONS) / EARLY APRIL FOR 1ST PUBLIC MEETING POSSIBLY MEET / REVIEW WITH SELECTBOARD IN ADVANCE FOR PREVIEW

3. FEEDBACK

PB, MCG, KL TO REVIEW AND PROVIDE FEEDBACK INCLUDING PROGRAMMING PREFERENCES, WITH AREA. ADJACENCY REQUIREMENTS. IDEALLY FEEDBACK RECEIVED SOONER THAN LATER WHILE FRESH IN MEMORY.



ISLE LA MOTTE